



Product End-of-Sale Notice: XFP and CFP Transceiver Modules

Notification Date: November 1, 2016

Dear Customer,

This is a formal end-of-sale notice for the XFP and CFP form-factor transceiver modules, which are not compatible with our current product portfolio. This affects the following part numbers:

- **VX_00012** **XFP,10Gbase-ER,SM,Xcvr**
- **VX_00014** **XFP,10Gbase-LR,SM,Xcvr**
- **VX_00015** **XFP,10Gbase-SR,MM,Xcvr**
- **VX_00016** **XFP,10Gbase-ZR,SM,Xcvr**
- **VX_00035** **CFP,100Gbase-LR4,SM,Xcvr,Diag**
- **VX_00036** **CFP,100Gbase-SR10,MM,Xcvr,Diag**
- **VX_00041** **CFP,100Gbase-ER4,SM,Xcvr,Diag**

The products and parts (SKUs) listed above are no longer available to quote or order, effective immediately. Support for these products will continue for a time, as specified by NETSCOUT Systems policy.

There are no replacements for these parts, however, if you have need of these transceivers for any of your existing VSS products, please contact NETSCOUT Tech Support or your local representative to obtain a list of supported manufacturers and manufacturer models.

Thank you for your cooperation in this product transition. We regret any inconvenience that discontinuing this platform may cause your organization.

Our sales and support staff are available to assist you in any way possible.

Product Management

VSS Monitoring Inc.